

C O P Y

CONFIRMED TO BE UNCLASSIFIED
 AUTHORITY DOE/SA-20
 BY D. R. GILSON, DATE 6-16-94
 ADD

June 13, 1970

Memorandum

To : Distad Rep Bikini

From : Sid Kirk, M-boat operator with AEC party

Subject : Observations on the conditions of the three M-boats stationed at Bikini Atoll, Marshall Islands, and recommendations.

Upon the request of Lewis Glenn, the District Administrator's Representative on Bikini Atoll, I have examined the three M-boats stationed at Bikini. I am a licensed First Mate on large craft and have been operating boats since 1964 for Global Associates, Kwajalein Atoll, Marshall Islands. Here follows my observations and recommendations.

The M-boat ramps:

1. Have holes and rust beyond repair.
2. Pad eyes rusty and could break and fall. One boat does not even have pad eyes and the bow ramp must be secured with rope.
3. Winches do not work properly; brakes will not hold; clutches are burned u
4. Handles to raise and lower the ramps are rusty and will not function prop
5. Belts on the winches are the wrong size and will not work properly.

The M-boat decks:

1. Rusty. Holes on top decks caused from rust.
2. Bits, cleats, and pad eyes all rusty and some broken.
- 3.

The M-boat engines:

1. Need complete overhaul.
2. Generators do not work.
3. Batteries will not keep a charge.
4. Bilge pumps do not work properly. Only one on each boat.
5. Throttles hard to maneuver, especially while making landings going from ahead to astern. Engines frequently stall when making this maneuver and leave the boat with power from only one engine, and sometimes with power from neither engine.
6. The screws are bent and out of balance. The shafts may also be in the same condition as there are bad vibrations when running at a high rpm. Three of the four engines on the two running M-boats will not reach over 1200 rpms.
7. There are no lights on the boats.
8. Most gauges on the control panel do not work.
9. Only safety equipment aboard the boats is life jackets and lined ring buoys. Signal flares are lacking. Emergency rubber life rafts are lacking. These items are essential, especially given the conditions of these boats.

C O P Y

5005180

7238-3108-

P061

1703

C O P Y

10. Need larger lines for the boats' anchors.

I conclude that these boats are unsafe and recommend that for the safety of the people who must use them that these boats should not be run until completely reworked, from bow to stern, or replaced.

/s/ Sid Kirk

Sid Kirk

C O P Y

5005181

7238-3108-0062

704