


November 18, 2010

PANTEX DROPPED PIECE OF HIGH EXPLOSIVES


The Event


- Quality Assurance Technicians (QATs) Performing Radiography of a High Explosives (HE) Part.
- HE manipulated through automated sequence to preset positions.
- Holding fixture designed to allow positioning of the HE for x-ray shots.
- Remote Operation, observed by closed circuit camera.
- QATs Noted HE Movement Within the Holding Fixture, Stopped Operation, But HE Part Slipped Out of Holding Fixture Onto a Padded Work Surface.




**INTERLOCK TO
PREVENT TILT**

**TOP RETAINING RING
OF THE ROTATION FIXTURE
(000-1-1380)**







**X-RAY DIGITAL
DETECTOR**


**HE ROTATION FIXTURE
(000-1-1380)**


X-RAY TUBE

**W COLLIMATOR
(000-2-1261)**

**INSPECTION TABLE
(800-2-0393)**

**X-RAY HEAD STAND
(000-2-1458)**









Causes

- The roller on the fixture rolled into an undulation in the HE surface and allowed the HE Part to drop enough to become dislodged.
- The Holding Fixture did not prevent the HE Part from falling to the table.


Bottom Roller Position





Causes (Continued)

- The undulations in HE surface were not out of tolerance for the measurement method (Shadow Graph) in use.



**Actual Contour
Back Drive Roller**

**Actual Contour
Front Rollers**

**Outer Limit of
Shadow Graph**

**Inner Limit of
Shadow Graph**



Causes (Continued)

- X-ray being used was not capable of shooting through an entire HE Part. Required part to be manipulated.

Corrective Actions

Re-Engineer process to address Holding Fixture being able to secure the HE Part for the whole range of acceptable dimensions and surface imperfections.

- Redesign HE Rotation Fixture.
- Evaluate other methods to identify undulations on HE Part.
- (Long-Term) Design and Construct New Facility.