Reproduced from the holdings of the National Archives
Pacific Southwest Region

REPORT
COLLECTION
BOX
FOLDER

PRESIDENT	
EXECUTIVE VPS	
VP FINANCE MGR	
ADVERTISING MGR	
ASST GEN MGR	
GEN CONST	
PUBLIC RELATIONS	
PROCUREMENT	
ESTIMATING	
OFFICE MANAGER	
HD OF ENGR	
CHIEF ENGR	
ENGR	
ENGR	
SALES	
ACCOUNTING	
SECURITY	

MSF07
RR UWL A

DF UHPJ 38
T LA254
R 222128

ATC CR18

DEPARTMENT OF ENERGY DECLASSIFICATION REVIEW
SINGLE REVIEW AUTHORIZED BY: ADS
REVIEWER (ADD): NAME: D. CAMP
DATE: 2/1/91
DETERMINATION (CIRCLE NUMBERS)
1 CLASSIFICATION RETAINED
2 CLASSIFICATION CHANGED TO
3 CONTAINS NO DOE CLASSIFIED INFO
4 COORDINATE WITH
5 CLASSIFICATION CANCELLED
6 CLASSIFIED INFO ERASED

RECEIVED

~~SECURITY INFORMATION~~
~~RESTRICTED~~

FROM LOW NAN INTW

TO LOW NAN LOCA

CITY ENGMSG TWO LEVEL VERTICAL A

~~RESTRICTED~~

DAVE NARVEA J FOLLOWING LOCK SCREW A EIGHT FOUR FIVE THREE

ADDITIONAL DAMAGE TO STATION PHOTO SHOWS ONE EXTENSIVE PD

FRONT ELEVATION STATION FIRST AND SECOND FLOORS SHOWS THREE MAJOR

DIAGONAL CRACKS NO DAMAGE ABOVE SECOND FLOOR PD END ELEVATION

BETWEEN FIRST AND SECOND FLOORS SHOWS FIVE MAJOR DIAGONAL CRACKS IN END

PANELS AND VERTICAL CRACK BETWEEN PD NORTH AND COLUMN BAKER

PD NO DAMAGE ABOVE SECOND FLOOR CONCRETE FLOOR WALL

PANEL BETWEEN COLUMNS CHARLIE AND DOG SHOWS AND STEEL COLUMNS ROUTED

PD REAR ELEVATION SECOND FLOOR AND FIRST FLOORS SHOWS

VERTICAL CRACKS AT COLUMNS FOR BOTH CONCRETE PANELS AND SIX

MAJOR DIAGONAL CRACKS IN STATION BRICK WALLS AT BETWEEN SECOND AND

THIRD FLOORS MINOR PARTS BEGINNING TO CHIPPED AWAY FROM CONCRETE COLUMNS

SMOLN CORNER PARTS MISSING AND NO APPARENT MAJOR STRUCTURAL

DAMAGE TO ANY CONCRETE COLUMNS OR TRUSSES NO DATA FROM TWO PANELS SEVEN

SIX NOT RECEIVED

22/2150

"This material contains information affecting the national defense of the United States within the meaning of the espionage laws, Title 18, U.S.C., Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law."