

SECURITY INFORMATION

REPOSITORY
COLLECTION
BOX No
FOLDER

LX41

TUB25

HA090

PP UWGX

DE UHPJC 54

T LA254

P 252131Z



RECEIVED

AEC GRNC

RESTRICTED	
EXEC VICE PRES	
V PRES & GEN MGR	
CH FISCAL OFFCR	
ASST GEN MGR	I
OPER-CONST	I
INT'L RELATIONS	
PROCUREMENT	
ESTIMATING	
OFFICE MANAGER	
DIR OF ENGRNG	
CH DESIGN ENGR	
CH PRODUC	
EDG ENGR (884)	
SALTS DIVISION	
ACCOUNTING	
SECURITY	

R
A on front

"This material contains information affecting the national defense of the United States within the meaning of the espionage laws, Title 18, U.S.C., Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law."

Baker

FROM HOW NAN ENIWTOK

TO HOW NAN LOSA

RESTRICTED

CITE ENMSG FOUR ONE SIX EIGHT

6249

DAVID NARVER JR FROM DIETZE PD REF DRAWING SIX TWO FOUR

NINE CMM STATION ONE TWO ONE ZERO CMM DOOR INTO INSTRUMENT ROOM PD

PLEASE ADVISE VERTICAL REINFORCING STEEL REQUIRED ON EITHER SIDE OF

DOOR

AC

25/21352

DEPARTMENT OF ENERGY DECLASSIFICATION REVIEW	
SINGLE REVIEW A THOROUGHLY DETERMINED THAT NO INFORMATION CONTAINED HEREIN IS DANGEROUS TO NATIONAL SECURITY	AAS:unsgall/ 7/23/94
REVIEWER (ADM)	NAME: J.D. AARON
DATE	7/23/94

BEST COPY

SECURITY INFORMATION
RESTRICTED

Answer 9/28

4168

The next day the door was delivered and
consisted of a single sheet of metal.
It was to be bolted to the wall
in a thin gap between the door and
the frame. There was no gap between

the door and the frame. Spacing between